

**AEROSTAR INTERNATIONAL, INC.
SERVICE LETTER 109**

November 9, 1994

SUBJECT: CLARIFICATION OF SERVICE BULLETIN 122 ISSUED
JANUARY 15, 1987

PROBLEM: There have been reports that the cable backup system
utilized on this service bulletin are not being installed on TW
baskets that have stainless steel superstructures and lower
frames.

DISCUSSION: It has been determined that the aluminum interface pins on
these baskets will bend or break when flown at gross lift
conditions in wind or restraint circumstances creating
abnormal stresses or torquing of the superstructures.

APPLICABILITY: All Classic IX and X baskets with serial number prefixes
starting with TW.

**CORRECTIVE
ACTION:** Compliance with Service Bulletin 122, the installation of a
cable back-up system.

PROCEDURE: Follow procedures on Service Bulletin 122. Cable back-up
system furnished by Aerostar International, Inc.

If you have any questions contact:

Dee M. Rose
Customer Service Manager
AEROSTAR INTERNATIONAL, INC.
P.O. BOX 5057
SIOUX FALLS, SOUTH DAKOTA 57117
PHONE: 605-331-3500
FAX: 605-331-3500